

DATE 0720Z 02 JAN 63

TOP SECRET

1	10
2	11
3	12
4	13
5	14
6	15
7	16
8	17

TO : DIRECTOR

25X1A FROM : [REDACTED]

ACTION: OPS 1-12

INFO :

PRIORITY

25X1A

IN 56930

TOR: 0835Z 02 JAN 64

25X1A TO PRIORITY [REDACTED] INFO PRIORITY [REDACTED]

25X1A [REDACTED]

A. 6071

B. 112A CAMERA/7356 FEET [REDACTED]

25X1A

C. PROCESSED ON TRENTON NUMBER 2/AT MAXIMUM DEVELOPMENT
THROUGHOUT/PRIMARY 74, SECONDARY 67.5 DEGREES F.

D. GAMMA HEAD 2.41 TAIL 2.42.

E. 4404 - (SO-132)/45-74-11-3.

F. QUALITY EVALUATION:

1. GOOD RECEIVED ON 4 SPOOLS
2. APPEARS SLIGHTLY UNDER EXPOSED
3. CONTRAST IN PERCENT - 90 LOW, 10 MEDIUM.
4. GOOD
5. GOOD
6. GOOD
7. N/A

G. A MINUS DENSITY STREAK, APPROXIMATELY 0.2 INCHES
WIDE OCCURS ON EACH FRAME DURING THE LAST TWO-THIRDS OF THE
MISSION. THIS STREAK IS 0.10 INCHES FROM THE TRAILING

TOP SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1A

[] (IN 56930) TOP SECRET PAGE TWO
PORT EDGE AND 0.25 INCHES FROM THE TRAILING STARBOARD
EDGE, OF THE FORMAT AREA ON EACH FRAME. IMAGERY IS SOME-
WHAT DEGRADED IN THIS MINUS DENSITY STREAK WHICH BECOMES
PROGRESSIVELY WORSE TOWARD THE END OF THE MISSION. DURING
APPROXIMATELY THE LAST ONE THIRD OF THE MISSION THIS STREAK
APPEARS TO SPLIT INTO TWO PARALLEL MINUS DENSITY STREAKS.
BANDING IS PRESENT 4 TO 5 INCHES INTO THE FORMAT AREA
FROM THE PORT SIDE OF EACH FRAME. FOUR SHORT SCRATCHES
OCCUR 0.2, 1.9, 3.1, AND 4.0 INCHES FROM THE PORT EDGE OF
EACH FRAME. THESE SCRATCHES ARE ALONG THE LEADING EDGE
OF THE FILM AND ARE OUTSIDE THE FORMAT AREA. LEADING AND
TRAILING EDGE STATIC FOGGING OCCURS ON THE FIRST ONE
THIRD OF THE MISSION. THE TAKE ARRIVING IN 4 SEPARAGE
SPOOLS CAUSED A SMALL PORTION OF FRAMES 402, 1158, AND
1898 TO BE DAMAGED DUE TO THE CUT AND SPLICE. THERE ARE
2642 TITLED FRAMES. CLOUD COVER IS APPROXIMATELY 20
PERCENT.

END OF MSG

T O P S E C R E T